



P.O. Box 326326 Hagatna, GU 96932  
 Office: (671) 648-FIRE (3473)  
 Email: sales@falconfireguam.com  
 CLB 08-0377 C19 & C20

## STANDPIPE AND HOSE SYSTEMS INSPECTION REPORT

DATE OF INSPECTION	
Wednesday, June 06, 2018	

TECHNICIAN'S NAME	Eric Peredo	W.O.#	5001
JOB INFORMATION	Alupang Cove Condominiums		
PHYSICAL ADDRESS	241 Condo Lane Tamuning, GU 96913		

TYPE OF INSPECTION	
NEW INSTALL	
ANNUAL	X
SEMI-ANNUAL	
OTHER	

COMPANY INFORMATION	
Name:	Alupang Cove Condominiums
Contact Name:	Davin
Address:	241 Condo Lane Tamuning, GU 96913
Email:	acove@teleguam.net
Office#:	(671) 649-6190
Mobile#:	

### 1. General

a. Location of control valve Fire Hose Cabinet

b. Type of system  
 None  Class I  50 ft (15m)  Class II  75 ft (23m)  Rubber lined  Class III  100 ft (30m)  Unlined

c. Length of hose provided

d. Type of hose provided  
 (If unlined hose is presently installed, it may remain in use. However, when it requires replacement only lined hose should be used in accordance with NFPA 14.)  
 Yes  No

e. Are shutoff nozzles provided?  
 (If "no," nozzles should be replaced with shutoff type in accordance with NFPA 14.)  
 Yes  No

f. Are pressure regulating devices provided?

g. Type of regulating devices

### 2. Valves

a. How are valves supervised?  
 Sealed  Locked  None  N/A   
 Yes  No

b. Are valves identified with signs?

### 3. Water Supply

a. When was last water supply test made? 6/6/2018 65 PSI  
 Yes  No  N/A

b. Are reservoirs, tanks, or pressure tanks in good condition?

### 4. Pumps

a. Is fire pump  
 Diesel  Electric  Gasoline  None   
 Yes  No  N/A

b. Is pump in good condition?

c. When was pump last tested?

### 5. Fire Department Connections

a. Location Entrance of property/main gate

b. Are identification signs provided?  
 Yes  No

### 6. Notes

APPROVED FOR ISSUE BY	
	DATE: 6/7/2018
X	CERTIFIED
	NOT CERTIFIED

ALL INSPECTIONS AND MAINTENANCE WERE PERFORMED IN ACCORDANCE WITH N.F.P.A. AND MANUFACTURERS STANDARDS AND SPECIFICATIONS.

Next Due June 6, 2019